

# Scotchlok<sup>™</sup> Insulation Displacement Electrical Tap Connector 801

# **Data Sheet**





## **Application**

Use Scotchlok™ Tap Connector 801 to electrically connect a (tap) wire end to a through (run) wire, join parallel run wires, and insulate the connection.

#### Wire Range

18 -16 AWG (0,75-1,0mm²) solid or stranded, 14 AWG (1,5mm²) solid or stranded, tinned or untinned copper conductors. For use with thermoplastic insulated wires such as: T, TW, TFF, TFN, TFFN, AWN, TEW, SAE-GPT, with a maximum insulation diameter of .145 inches (3,5 mm).

Maximum recommended current for general purpose applications: 18 AWG - 7 Amps, 16 AWG - 10 Amps, 14 AWG - 15 Amps

#### Construction

U-Contact - Tin plated brass, .03 in. thick (0,8 mm)
Insulator - Polypropylene
Color - blue

#### Weight

.0032 lb. (1,45 gm)

#### **Recommended Installation Tools**

3M<sup>™</sup> Crimping Tool No. E-9BM 9" Linemans Pliers

## **Engineering Specification**

Insulation Displacement Connector (as manufactured by 3M, part No. 801) capable of connecting a tap wire to a run wire in the range of 18-16 AWG (0,75-1,0mm²) solid or stranded, and 14 AWG (1,5mm²) stranded, tinned or untinned copper conductors. The connector shall be UL Listed for 600 Volts maximum building wire: 1000 Volts maximum, signs fixtures and luminaires, and have a maximum insulating temperature of 105°C (221°F).

# **Regulatory Agencies**

UL Listed as a Pressure Cable Connector Tested per UL Standard 486C UL File No. E23438 Operating Temperature: 105°C (221°F) Voltage Rating: 600 volts max. building wire; 1000 volts max. signs and fixtures Flammability Rating: UL94 V-2


CSA Certified-CSA Standard C22.2 No. 0, 188-M1983

CSA File No. LR15503

Operating Temperature: 105°C (221°F) Voltage Rating: 600 volts max. building wire 1000 volts max. signs and luminaires. Flammability Rating: C22.2 No. 0.6 V-2

# **Federal Specification W-S-610:**


	"Commercial	package only"	
Type	Class	Kind	Style
1	1	cu	G



#### **Installation Instructions**

# **AWARNING**

Turn power off before installing or removing terminal. All electrical work should be done according to appropriate electrical codes.



- 2. Insert unstripped tap wire completely.
- 3. Hold tool perpendicular to the wire and make the connection by crimping the u-contact down flush with the top of the plastic insulator.
- 4. Close top hinged cover until latched.



Tap / Run Connection



**Parallel Connection** 

3M and Scotchlok are trademarks of 3M Company.



is a trademark of Underwriters Laboratories.



is a trademark of Canadian Standards Association.

#### **IMPORTANT NOTICE**

Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use.

Warranty; Limited Remedy; Limited Liability. This product will be free from defects in material and manufacture as of the date of purchase. 3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. Except where prohibited by law, 3M will not be liable for any loss or damage arising from this 3M product, whether direct, indirect, special, incidental or consequential regardless of the legal theory asserted.



**Electrical Products Division**